


To run without the detector (when the detector is broken) function setting [NOS.ON]

- (1) **Call out the program mode [A] function [NOS].**

(This can be called with mode call or direct number call. Refer to pages 17 to 20.
(Direct call number = "0112"))



* Press the [D] key and set the value to "ON".

- (3) **Entering the normal mode**

For mode call: [↓] + [↑]

For direct number call: Set with **Enter** and then press **Parameter Setup**.

Description

- A. Only variable-speed operation will be possible. Set position stopping and thread trimming will not be possible
- B. Each time the [D] key is pressed, the setting will alternate between [OF] and [ON]